



Simon Lucas Mitsubishi
 Cnr Wairau & Target Roads
 Wairau Valley, AUCKLAND 0627
 +64 9 443 9873
 www.simonlucas.co.nz

Vehicle Scan Summary · 29/07/2022 08:31

Scan Result



Possible Service







Diagnostic Notes

- Rotate tyres, if needed, based on manufacturer and vehicle specifications.



Braking Distance

(113 KPH - Wet Surface)



Good

Marginal

Replace Now